


Report No.: SZ20081701A Date: 2020/08/17

TEST REPORT



Suzhou ASTTEK Testing Technology Co Ltd IQ Center























In no circumstances shall the company is responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected tested and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced

Add: No.8, Shiyuan Raod, Beiqiao, Suzhou, China Fax: +86-512-65769481

Tel: +86-512-65764782 Http://www.asttek.com

TEST REPORT

			No.		
PRODUCT NAME	Chemotherapy gown				
TYPE/MOD EL	St. St.	<u> </u>	at State of		
TEST KIND	Sample test	CHECK NUMBER	SZ20081701A		
CUSTOMER	Zhejiang huafu medical equipment Co.,ltd	UNIT ADDRESS	No.688,Xinxing 1st Road,Pinghu,Jiaxing City,Zhejiang Province,314200		
MANUFACT URER	Zhejiang huafu medical equipment Co.,ltd	SAMPLE DATE	2020.08.12		
RECEIPT	Post	TEL.	0573-85098336		
TEST STANDARD	ASTM F 739-12 Standard Test Method for Permeation of Liquids and Gases through Protective Clothing Materials under Conditions of Continuous Contact				
TEST DATE	2020.08.13-2020.08.15				
CONCLUSI ON	See page 3 for test results				
REPORT MAKER	☆]〜 CHECK	吴炜	APPROVAL 3th		

In no circumstances shall the company is responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected tested and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

Date: 2020/08/17

Page: 3 of 5

TEST RESULTS

NO.	TESTING ITEMS	SPECIFICATIONS	TEST RESULTS	DETERMI NATION
14	Carmustine	And the state of t	Not penetrated	P
2	Cisplatin		Not penetrated	Р
3	Cyclophosphamode		Not penetrated	P
4	Dacarbazine	55"	Not penetrated	Р
5	Doxorubicin Hydrochloride	1. The sample is placed in the required environment (temperature: 27°C, relative humidity: 55%RH) for 24	Not penetrated	P
6	Etoposide	hours. 2. After weighing and selecting the sample, install it	Not penetrated	P
7	Fluorouracil	in the test chamber, and set the flow rate as 100cm ³ /min,test for 480min.	Not penetrated	Р
8	Methotrexate	3.Observe the penetration state of test liquid.	Not penetrated	Р
9	Mitomycin C	Page Page 1	Not penetrated	P
10	Paclitaxel		Not penetrated	P
11	Thiotepa		Not penetrated	P
12	Vincristine Sulfate	25th	Not penetrated	P
5"	REMARKS	The samples were all tested under the required t	echnical environmenta	l condition.

"P" represents pass; "F" represents failure; "N" represents not happen; "---" represents not content.

In no circumstances shall the company is responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected tested and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

Add: No.8, Shiyuan Raod, Beiqiao, Suzhou, China

Fax: +86-512-65769481

Tel: +86-512-65764782 Http://www.asttek.com Report No.:SZ20081701A Date: 2020/08/17 Page: 4 of 5

SAMPLE PICTURE




*****Continue on next page*****

In no circumstances shall the company is responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected tested and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced except in full.

 Add: No.8, Shiyuan Raod, Beiqiao, Suzhou, China
 Tel: +86-512-65764782

 Fax: +86-512-65769481
 Http://www.asttek.com

STATEMENT





2. All the information for the samples will be protected by us ,no any will be leaked out.

3. The samples can be kept in our lab for one week, later it will be disposed based on the regulation of the Lab.

4. The test result of the samples are the reference only, we are not responsible for other products.

5. When disputing, the client can request Jiangsu arbitration commission to handle it.

In no circumstances shall the company is responsibility extend beyond inspection, testing and reporting upon the samples actually drawn from the bulk and inspected tested and at the sole and exclusive responsibility of the Principal. This test report cannot be reproduced